

ALARACT 253/2014

DTG: 181746Z NOV 14

UNCLAS FOR OFFICIAL USE ONLY

SUBJ/ALARACT 253/2014 - ACTIVE ARMY & ARMY RESERVE TURN-IN OF DEFECTIVE AN/UDR-13 POCKET RADIAC, NSN: 6665-01-407-1237; LIN: R31061, SERIAL NUMBERS: 06800C-32855C

THIS MESSAGE HAS BEEN TRANSMITTED BY USAITA ON BEHALF OF HQDA DCS G-4//DALO-MNI//

REFERENCES:

REF/A: GROUND PRECAUTIONARY ACTION (GPA) 2014-005, COMMUNICATIONS ELECTRONICS COMMAND (CECOM), DTG: 291551Z MAY 2014, SUBJECT: TURN-IN OF DEFECTIVE AN/UDR-13 POCKET RADIAC, NSN: 6665-01-407-1237; LIN R31061, SERIAL NUMBERS: 06800C-32855C, 29 MAY 14

REF/B. DA PAM 710-2-1 USING UNIT SUPPLY SYSTEM (MANUAL PROCEDURES), 31 DEC 97

REF/C. DLM 4000.25-1 MILITARY STANDARD REQUISITIONING AND ISSUE PROCEDURES (MILSTRIP), 13 JUN 12

REF/D. AR 750-43 ARMY TEST, MEASUREMENT AND DIAGNOSTIC EQUIPMENT, 24 JAN 14

1. (FOUO) BACKGROUND.

1.A. (FOUO) THE AN/UDR-13 IS A TACTICAL INDIVIDUAL ELECTRONIC DOSIMETER THAT MEASURES RADIATION. ANY AN/UDR-13 THAT HAS A SERIAL NUMBER THAT FALLS WITHIN THE RANGE OF 06800C-32855C HAS A DEFECTIVE BOARD. THE DEFECT WILL CAUSE THE AN/UDR-13 TO PERIODICALLY ALARM AND THEN RESET. THIS PERIODIC MOMENTARY "BEEPING" MAKES THE AN/UDR-13 UNSUITABLE FOR TACTICAL OPERATION WHERE NOISE DISCIPLINE IS REQUIRED.

1.B. (FOUO) THIS MESSAGE IS A DIRECTIVE TO ACTIVE ARMY AND RESERVE UNITS WITH DEFECTIVE BOARDS. THESE DEFECTIVE BOARDS WILL BE REPLACED AT NO COST TO THE UNIT.

2. (FOUO) EFFECTIVE IMMEDIATELY, THE ACTIVE ARMY AND ARMY RESERVE UNITS THAT HAVE AN AN/UDR-13 WITH A SERIAL NUMBER WITHIN THE RANGE OF 06800C-32855C MUST TURN-IN THEIR DEFECTIVE ASSET IN "AS IS" CONDITION WITH ITS CARRYING CASE.

2.A. (FOUO) PRIOR TO TURN-IN, THE UNIT MUST REMOVE THE BATTERIES FROM THE AN/UDR-13.

2.B. (FOUO) THE UNIT MUST ALSO PREPARE TURN-IN DOCUMENT DA FORM 2765-1, REQUEST FOR ISSUE OR TURN-IN, IN ACCORDANCE WITH, DA PAM 710-2-1. THE DEFECTIVE AN/UDR-13 MUST BE CODED CONDITION "G" PRIOR TO TURN-IN. ALTERNATIVELY, A DD FORM 1348-1A, ISSUE RELEASE/RECEIPT DOCUMENT, CAN BE USED WHEN SENDING ASSETS IN FOR REPAIR IN ACCORDANCE WITH, DLM 4000.25-1

3. (FOUO) UNITS WITH A DEFECTIVE AN/UDR-13 WILL SEND TO CECOM DIRECTORATE FOR SAFETY: DODAAC W906DE W4GV USA HQ COMM ELECT CMD, 3200 RARITAN AVE ABERDEEN PROVING GROUND MD 21005-5001, CECOM POINT OF CONTACT IS MR. BURT CUMMINGS, HEALTH PHYSICIST, COMMERCIAL (443) 395-3788; EMAIL: BURTON.C.CUMMINGS.CIV@MAIL.MIL.

DISREGARD THE SHIP TO ADDRESS IN THE GROUND PRECAUTIONARY ACTION.

3.A. (FOUO) UNITS ARE AUTHORIZED TO USE ARMY TRANSPORTATION ACCOUNT CODE A2ZA WHEN SENDING THE DEFECTIVE AN/UDR-13 TO THE CECOM SAFETYLABORATORY.

4. (FOUO) UNITS MUST INFORM THEIR TEST, MEASUREMENT, AND DIAGNOSTIC EQUIPMENT (TMDE) SUPPORT ACTIVITY OF THE TURN-IN. THIS WILL ALLOW THE TMDE SUPPORT ACTIVITY TO UPDATE THEIR TMDE INTEGRATED MAINTENANCE MANAGEMENT SYSTEM (TIMMS) IN ACCORDANCE WITH, AR 750-43.

4.A. (FOUO) UNITS MUST ALSO UPDATE THEIR UNIT PROPERTY BOOK UNIT SUPPLY ENHANCED (PBUSE) TO REFLECT THE TURN-IN.

5. (FOUO) CONCURRENT WITH THE TURN-IN, UNITS MUST SUBMIT A REQUISITION THROUGH THE SUPPLY SYSTEM FOR A REPLACEMENT AN/UDR-13.

5.A. (FOUO) ONCE UNIT RECEIVES A REPLACEMENT AN/UDR-13, THEY MUST UPDATE THEIR PROPERTY BOOK.

5B. (FOUO) UNIT MUST ALSO PROVIDE NEW SERIAL NUMBER TO THE TMDE SUPPORT ACTIVITY. THIS ALLOWS THE TMDE SUPPORT ACTIVITY TO UPDATE THEIR TIMMS DATABASE IN ACCORDANCE WITH, AR 750-43.

6. (FOUO) REQUEST ARMY COMMANDS, ARMY SERVICE COMPONENT COMMANDS, AND DIRECT REPORTING UNITS ASSIST IN ENSURING WIDEST DISSEMINATION OF THIS MESSAGE.

7. (FOUO) HQDA G-4 POINT OF CONTACT IS INTEGRATED LOGISTICS SUPPORT DIVISION (DALO-MNI) MS. CHRISTINE KING, CHRISTINE.M.KING6.CIV@MAIL.MIL, 571-256-4889, OR DSN 260-4889.

8. (FOUO) THIS MESSAGE EXPIRES ON 30 SEPTEMBER 2015.